VOLUME XII. INDEX

	Quarterly No.	Page No.
A		
Aeroplane Factory Fire, Marblehead, Mass	3	311
Airplane Manufacture, Features of Fire Hazard in	4	345
Army Hospitals, How Protected against Fire	1	59
Automatic Sprinklers, Annual Summary	4	410
B		
"Best Building" Competitions in Cleveland	3	242
Building Collapse and Fire, Sioux City	2	204
Button Factory Holocaust, Newark, N. J	2	180
C		
Chlorate of Potash, Note on	1	71
Chlorates, The	1	67
Comparative Cost of Fire-Resistive Construction	4	343
Comparative Statistics of Fire Loss	1	38
D		
Distillery Fire, Green River, Ky	2	214
Drip Valve Tests, Experiments on	2	163
Dry Pipe Sprinkler Systems in Refrigeration Rooms	3	275
Drying Oils, Fire Hazard of the Newer	3	283
E		
Editorial: No. 1, page 5; No. 2, page 117; No. 3, page 229	4	329
Electrical Apparatus, Housing of Outdoor	2	155
Electrical Inspection, Importance of to the Public	4	355
Electrical Transformer Failure Caused by Oil Leakage	1	37
Executive Committee Meeting	1	14
Extinguishers, Notes on Hand Fire	2	173
F		
Factory Water Supplies, Planning for Safety	1	76
Fertilizer Factory and Railroad Terminal Fire, Savannah	4	405
Film Exchange Fire, Kansas City	2	209
Film Exchange Fire, Pittsburgh	4	393
Fire Alarm Station at San Francisco, Central	4	374
Fire and Accident Prevention Day, 1918	3	237
Fire Causes: No. 1, page 107	3	322
Fire Departments, Strikes in	1	55
Fire Loss, Comparative Statistics of	1	38
Fire Losses, 1918	3	234
Fire Prevention Bureau of Chicago	2	149
Fire Prevention Convention and League, Ontario	2	120
Fire Prevention Exhibition Suggestions	2	122
Fire Prevention Section, War Industries Board, Report of	1	19
Fire Protection History, An Excursion into	1	21

VOLUME XII. INDEX

	Quarterly No.	Page No.
A		
Aeroplane Factory Fire, Marblehead, Mass	3	311
Airplane Manufacture, Features of Fire Hazard in	4	345
Army Hospitals, How Protected against Fire	1	59
Automatic Sprinklers, Annual Summary	4	410
B		
"Best Building" Competitions in Cleveland	3	242
Building Collapse and Fire, Sioux City	2	204
Button Factory Holocaust, Newark, N. J	2	180
C		
Chlorate of Potash, Note on	1	71
Chlorates, The	1	67
Comparative Cost of Fire-Resistive Construction	4	343
Comparative Statistics of Fire Loss	1	38
D		
Distillery Fire, Green River, Ky	2	214
Drip Valve Tests, Experiments on	2	163
Dry Pipe Sprinkler Systems in Refrigeration Rooms	3	275
Drying Oils, Fire Hazard of the Newer	3	283
E		
Editorial: No. 1, page 5; No. 2, page 117; No. 3, page 229	4	329
Electrical Apparatus, Housing of Outdoor	2	155
Electrical Inspection, Importance of to the Public	4	355
Electrical Transformer Failure Caused by Oil Leakage	1	37
Executive Committee Meeting	1	14
Extinguishers, Notes on Hand Fire	2	173
F		
Factory Water Supplies, Planning for Safety	1	76
Fertilizer Factory and Railroad Terminal Fire, Savannah	4	405
Film Exchange Fire, Kansas City	2	209
Film Exchange Fire, Pittsburgh	4	393
Fire Alarm Station at San Francisco, Central	4	374
Fire and Accident Prevention Day, 1918	3	237
Fire Causes: No. 1, page 107	3	322
Fire Departments, Strikes in	1	55
Fire Loss, Comparative Statistics of	1	38
Fire Losses, 1918	3	234
Fire Prevention Bureau of Chicago	2	149
Fire Prevention Convention and League, Ontario	2	120
Fire Prevention Exhibition Suggestions	2	122
Fire Prevention Section, War Industries Board, Report of	1	19
Fire Protection History, An Excursion into	1	21

	Quarterly No.	Page No.
F		
Fire–resistive Construction Cheaper in First Cost	4	343
Fire Service, The Human Factor in the	3	245
Flour Mills, Loose Fan Hazard in	4	366
Forest Conflagrations in Northern Minnesota	3	285
Fuel Oil Hazards, Fire Record	1	90
H		
High Pressure Fire Service Mains, Leaks from	1	72
Hose, Substitution of Cotton and Hemp Yarns for Linen Yarns in Unlined	2	168
Hospitals, Army, How Protected against Fire	1	59
Hospital Holocaust, Central Oklahoma	1	98
Housing of Outdoor Electrical Apparatus	2	155
Human Factor in the Fire Service, The	3	245
J		
Japan and Lacquer Hazards. Fire Record	3	291
K		
Kapok and Its Hazards	3	261
Kerosene Oil Burners	2	161
L		
Lacquer Hazards, Japan and. Fire Record	3	291
Leaks from High Pressure Fire Service Mains	1	72
Leather Dyes, Stains and Finishes	4	381
Lightning Arrester Performance, Influence of Ground Connections on	1	65
Loss of Life, Fires in which there was	3	317
Loss of Life from Common Hazards	1	29
M		
Molasses Tank, Collapse of	4	371
Motion Picture Film Exchange Fire, Kansas City	2	209
Motion Picture Film Exchange Fire, Pittsburgh	4	393
Motion Picture Projector, The Portable	3	253
O		
Office Building Fire, Rochester	2	199
Oil Dock Fire, Seattle	3	301
Oil Leakage Causes Transformer Failure	1	37
Oil Storage on Waterfront at Seattle (*Illustration*)	2	116
Oils, Fire Hazard of the Newer Drying	3	283
Ontario Fire Prevention Convention and League	2	120
Outdoor Electrical Apparatus, Housing of	2	155
Oxygen Tank Explosion, Austin, Texas	2	176
P		
Points of Interest from Fire Reports	1	102
Portable Motion Picture Projector, The	3	253

	Quarterly No.	Page No.
P		
Potash, Chlorate of, Note on	1	71
Public Records, The Care of	3	250
R		
Railroad Terminal and Fertilizer Factory Fire, Savannah	4	405
Refrigeration Rooms, Dry Pipe Sprinkler Systems in	3	275
Rubber Industry, New Hazards in	1	83
Rubber Works. Fire Record	2	183
S		
Saskatchewan Fire Prevention Act and Its Administration	4	334
School Buildings, Standardization of	1	49
Schools, Fire Safety in	2	129
Shingle Roof Conflagration, Fulton, S. D.	1	16
Shingle Roof in China (*Illustration*)	1	18
Ship Fires, How some Important were Fought	2	143
Ships, Fighting Fires in	4	352
Ships, The Fire Risk on	2	133
Shipyard Fire Protection	2	126
Sprinkler Equipments, Maintenance of During Cold Weather	2	157
Sprinkler Systems, Dry Pipe in Refrigeration Rooms	3	275
Sprinklers, Testing of City Water Supply for	3	257
Stationary Chemical Extinguisher with Sprinkler Heads Operates on Fire	1	101
Statistics of Fire Loss, Comparative	1	38
Steam Coil, Charring of Wooden Supports by	1	28
Strikes in Fire Departments	1	55
Sulphur Colors	3	268
T		
Tobacco Waste and Fire Hazard	1	42
Transformer Failure Caused by Oil Leakage	1	37
U		
Unsatisfactory Sprinkler Fires	2	217
V		
Vessels, The Fire Risk on	2	133
W		
War Industries Board, Report of Fire Prevention Section	1	19
Warehouse (Jarvis) Fire, Jersey City	1	96
Water Mains, Fire Hydrants and Valves, Protection of in Winnipeg	2	159
Water Supplies, Factory, Planning for Emergencies	1	76
Water Supplies in Yard Mains, Maintaining	4	370
Water Supply, City, for Sprinklers, Testing of	3	257
Wooden Shingles, Prohibition of	4	367
Wooden Supports Charred by Steam Coil	1	28